

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

DATE: 4/12/87

SUBJECT: Potential Hazardous Waste Site

FROM: Keith Bradley, FIT RPO
Hazardous Waste Section (6E-SH)

SUPERFUND BRANCH

TO: Martha McKee, Chief
Compliance Section (6H-ES)

Site Name: Mitchell T. Halverson Site

Location: Hackberry, LA

EPA ID No.: LAD981910644 Thorn Lease

TDD No.: FG-8704-41

A. Deliverables:

- | | |
|---|--------------|
| 1. Preliminary Assessment (Form 2070-2) | attached () |
| 2. Site Inspection Report (Form 2070-3) | attached (X) |
| 3. Sampling Inspection Report | attached () |
| 4. Other: | attached () |

B. Were drinking water wells sampled? Yes () No (X)

C. Analytical Data:

- | | |
|-------------------------|--------------|
| 1. None collected | (X) |
| 2. Field data | () |
| 3. Contract lab results | attached () |
| 4. Houston lab results | attached () |

D. Comments:

Site is an active petroleum production
and separation facility which has three separators
and six storage tanks.

No further FIT action is recommended since
no apparent hazards were observed.

SUPERFUND
FILE

cc: (circle) Cabra 6H-S
Gazda 6E-E
Taylor 6H-CE

JUL 20 1987
REORGANIZED